

## Issues

| #    | Project                  | Status | Priority | Target version                              | Subject  | Assignee               | Updated             | Category          | Device                   | Upstream patch status |
|------|--------------------------|--------|----------|---|--|------------------------|---------------------|-------------------|--------------------------|-----------------------|
| 2354 | Replicant                | New    | Normal   | Replicant 6.0                               | Fix small typo on vendor_replicant-scripts/networking/usb/usb_networking_device.sh                         |                        | 04/10/2025 12:49 AM | Base applications | Not device specific      |                       |
| 2353 | Replicant                | New    | Normal   |   | Nonfree software found in vboot  |                        | 09/23/2024 03:46 PM | Freedom           | Not device specific      |                       |
| 2352 | Replicant                | New    | Normal   | Replicant 6.0 0005                          | Add letsencrypt certificate in Replicant 6.0   |                        | 06/18/2024 09:31 PM |                   | Not device specific      |                       |
| 2351 | Replicant infrastructure | New    | Normal   | Blog migration from Wordpress to CommonMark | Title issue in the new blog: the title is "- Replicant" instead of just Replicant or '<page> - Replicant'. |                        | 05/10/2024 03:26 PM |                   |                          |                       |
| 2350 | Replicant infrastructure | New    | Normal   | Blog migration from Wordpress to CommonMark | Use the same URLs than Wordpress in the new blog.  | Denis 'GNUtoo' Carikli | 05/08/2024 03:29 PM |                   |                          |                       |
| 2348 | Replicant infrastructure | New    | Normal   | Blog migration from Wordpress to CommonMark | Enable to comment inside the new blog.   | Denis 'GNUtoo' Carikli | 05/08/2024 03:28 PM | Blog              |                          |                       |
| 2347 | Replicant infrastructure | New    | Normal   | Blog migration from Wordpress to CommonMark | Import comments inside the new website.  | Denis 'GNUtoo' Carikli | 05/08/2024 03:28 PM | Blog              |                          |                       |
| 2346 | Upstreaming patches      | New    | Normal   |   | Port USBGuard to Android   |                        | 04/29/2024 10:20 PM |                   |                          | Work not started      |
| 2345 | Upstreaming patches      | New    | Normal   |   | Add USBGuard configuration for the Pinephone 1.2 in PostmarketOS.  |                        | 04/29/2024 10:20 PM |                   |                          | Work not started      |
| 2344 | Upstreaming patches      | New    | Normal   |   | Add basic support for the Pinephone 1.2 in Guix  |                        | 04/29/2024 10:19 PM |                   |                          | Work not started      |
| 2343 | Upstreaming patches      | New    | Normal   |   | Add support for multipart SMS in the GloDroid Radio HAL  |                        | 04/29/2024 10:19 PM |                   |                          | Work not started      |
| 2342 | Upstreaming patches      | New    | Normal   |   | Add support for cellular data in GloDroid Radio HAL  |                        | 04/29/2024 10:19 PM |                   |                          | Work not started      |
| 2341 | Upstreaming patches      | New    | Normal   |   | Add a package for an aarch64 gcc toolchain in Guix.  |                        | 04/29/2024 10:15 PM | Guix              |                          | Work not started      |
| 2339 | Replicant                | New    | Normal   | Any version                                 | x86 edition  |                        | 04/25/2024 07:53 AM | Devices           | New device               |                       |
| 2338 | Replicant                | New    | Urgent   | Replicant 6.0                               | Camera fault   |                        | 12/10/2023 07:34 PM | Camera            | Galaxy Note 2 (GT-N7100) |                       |

| #    | Project             | Status | Priority | Target version      | Subject   | Assignee | Updated             | Category                  | Device  | Upstream patch status |
|------|---------------------|--------|----------|---------------------|---|----------|---------------------|---------------------------|---|-----------------------|
| 2337 | Replicant           | New    | Urgent   | Replicant 6.0       | Bad system image for n7100  |          | 10/28/2023 07:26 PM |                           | Galaxy Note 2 (GT-N7100), Unknown   |                       |
| 2336 | Replicant           | New    | Normal   | Replicant 6.0       | No cellular network when backup and restore userdata.img                        |          | 07/19/2023 11:36 AM |                           | Galaxy S 3 (I9300)  |                       |
| 2335 | Replicant           | New    | Normal   | Any version         | Look into "git config format.subjectPrefix"                                     |          | 03/17/2023 10:59 PM | Website and wiki content  | Unknown   |                       |
| 2333 | Replicant           | New    | Normal   | Replicant 6.0 0004  | Cannot remove wallpaper   |          | 01/18/2023 08:07 PM | Graphics                  | Galaxy Tab 2 10.1 (P51xx)   |                       |
| 2332 | Replicant           | New    | Normal   | Any version         | Integrate DNSCrypt by default   |          | 01/18/2023 08:03 PM | Security                  | Not device specific   |                       |
| 2331 | Replicant           | New    | Normal   | Replicant 6.0 0004  | Color temperature and gamma settings don't work                                 |          | 01/18/2023 07:51 PM | Graphics                  | Galaxy S 3 (I9300), Galaxy Tab 2 10.1 (P51xx), Not device specific  |                       |
| 2330 | Replicant           | New    | Normal   | Replicant 6.0       | Improve recovery UI   |          | 01/18/2023 07:46 PM | Graphics                  | Not device specific   |                       |
| 2329 | Documentation       | New    | Normal   |                     | Outdated build documentation  |          | 01/18/2023 07:31 PM |                           |   |                       |
| 2328 | Replicant           | New    | Normal   | Any version         | libsamsung-ipc: OpenSSL 1.x is deprecated + OpenSSL 3.x license incompatibility |          | 12/30/2022 03:06 AM | Telephony and mobile data | Galaxy Nexus (GT-I9250), Galaxy Note (GT-N7000), Galaxy Note 2 (GT-N7100), Galaxy Note 8.0 (N51xx), Galaxy S (I9000), Galaxy S 2 (I9100), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx), Nexus S (I902x) |                       |
| 2327 | Upstreaming patches | New    | Normal   | Replicant 11.0 0001 | Fix AOSP manifest license   |          | 11/26/2022 06:43 AM | AOSP                      |   | Work not started      |
| 2326 | Upstreaming patches | New    | Normal   | Replicant 11.0      | Review Linux 6.0 userspace firmware related changes                             |          | 04/29/2024 09:57 PM |                           |   | Work not started      |

| #    | Project                  | Status | Priority | Target version                                | Subject  | Assignee | Updated             | Category                  | Device  | Upstream patch status |
|------|--------------------------|--------|----------|---|--|----------|---------------------|---------------------------|---|-----------------------|
| 2325 | Replicant                | New    | Normal   |   | Update <a href="https://redmine.replicant.us/projects/replicant/wiki/CommunityAndContact">https://redmine.replicant.us/projects/replicant/wiki/CommunityAndContact</a> |          | 11/07/2022 12:48 AM | Website and wiki content  | Not device specific   |                       |
| 2324 | Replicant                | New    | Normal   | Replicant 6.0                                 | Recovery image for n7100 missing from ftp-osl.osuosl.org?  |          | 01/18/2023 07:35 PM |                           | Galaxy Note 2 (GT-N7100)  |                       |
| 2323 | Replicant                | New    | High     | Replicant 6.0                                 | Galaxy NOTE 2 N7100 instalation and letter ussage bug  |          | 11/07/2022 12:51 AM |                           | Galaxy Note 2 (GT-N7100), Unknown   |                       |
| 2322 | Replicant                | New    | Normal   | Replicant 11.0 0001                           | Display panel "LDO25" regulator using 2.8v instead of 3.3v   |          | 10/08/2022 07:24 PM | Graphics                  | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)   |                       |
| 2321 | Replicant                | New    | Normal   | Replicant 11.0 0001                           | First installation: cannot reboot to normal from recovery  |          | 09/05/2022 03:14 PM |                           | Galaxy S 3 (I9300)  |                       |
| 2319 | Replicant                | New    | Normal   | Replicant 6.0 0004                            | Swiss SIM Cards not detected on i9300 with 6.0 0004  |          | 01/04/2023 01:43 AM | SIM card not recognized   | Galaxy S 3 (I9300)  |                       |
| 2318 | Replicant infrastructure | New    | Normal   |   | Switch to more simple IRC bridge   |          | 04/26/2022 11:49 AM |                           |   |                       |
| 2316 | Replicant                | New    | Normal   | libsamsung-ipc 1.0                            | libsamsung-ipc: support cross compilation  |          | 04/04/2022 01:00 PM | Telephony and mobile data | Not device specific   |                       |
| 2315 | Replicant                | New    | Normal   | Replicant 6.0                                 | [[USBNetworking]]: the usb_networking_device.sh is now shipped in Replicant 6.0 0004 images (and probably some of its RC)  |          | 10/09/2024 02:36 AM | Website and wiki content  | Not device specific   |                       |
| 2314 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Review AOSP mainline for code reuse and coperation   |          | 02/26/2022 11:37 PM |                           | Unknown   |                       |
| 2313 | Replicant                | New    | Normal   | Any version                                   | Look if we can ship a free WiFi firmware for the devices with a BCM4330  |          | 02/26/2022 11:36 PM | Wi-Fi                     | Galaxy Nexus (GT-I9250), Galaxy Note (GT-N7000), Galaxy S 2 (I9100), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx), Unknown |                       |
| 2311 | Replicant                | New    | Normal   | libsamsung-ipc 1.0                            | Handle endianness in multi bytes fields in libsamsung-ipc  |          | 04/04/2022 12:51 PM | Telephony and mobile data | Galaxy S 3 (I9300)  |                       |
| 2309 | Replicant                | New    | Low      | Any version                                   | Fix status of this wiki article or solve TODO  |          | 02/26/2022 08:08 PM | Website and wiki content  | Not device specific   |                       |

| #    | Project                  | Status      | Priority | Target version      | Subject  | Assignee                     | Updated             | Category                  | Device                                 | Upstream patch status |
|------|--------------------------|-------------|----------|---------------------|--|------------------------------|---------------------|---------------------------|--|-----------------------|
| 2308 | Replicant                | New         | Low      | Replicant 11.0      | Update wiki article information from replicant 10 to 11?               | _I3^<br>RELATIVIS<br>M       | 02/08/2022 12:47 AM |                           | Not device specific                    |                       |
| 2307 | Replicant                | In Progress | Normal   | Replicant 11.0 0001 | ipc-modem is unreliable  | Denis<br>'GNUtoo'<br>Carikli | 03/02/2022 12:55 PM |                           | Galaxy S 3 (I9300)                     |                       |
| 2306 | Replicant infrastructure | Feedback    | Low      |                     | Migrate our redmine wiki to Markdown format                            |                              | 02/02/2022 01:46 PM |                           |  |                       |
| 2305 | Replicant infrastructure | New         | Normal   |                     | git.replicant.us: can contributors delete master branches in contrib ? |                              | 02/02/2022 01:20 PM |                           |  |                       |
| 2304 | Replicant                | New         | Normal   |                     | Review GloDroid on the wiki  |                              | 01/30/2022 09:22 PM | Website and wiki content  | Not device specific                    |                       |
| 2303 | Replicant infrastructure | New         | High     |                     | Get our DNS mirrored by the FSF  |                              | 01/30/2022 08:13 PM |                           |  |                       |
| 2302 | Replicant                | New         | Low      | Any version         | Deprecate the use of "master" over "main" on source code Repositories  | _I3^<br>RELATIVIS<br>M       | 01/30/2022 08:05 PM | Infrastructure (web, git) | Not device specific                    |                       |
| 2301 | Replicant                | New         | Low      | Any version         | Improve theeming on Redmine Instance                                   | _I3^<br>RELATIVIS<br>M       | 01/27/2022 12:44 PM |                           | Not device specific                    |                       |
| 2299 | Replicant                | New         | Low      | Any version         | Add TODO lists to Replicant Redmine Instance                           | Denis<br>'GNUtoo'<br>Carikli | 02/02/2022 01:24 PM | Infrastructure (web, git) | Not device specific                    |                       |
| 2298 | Replicant                | New         | Low      | Any version         | new GDPR improvements-> website  |                              | 03/01/2022 10:36 PM | Website and wiki content  | Not device specific                    |                       |
| 2296 | Replicant                | In Progress | Normal   | libsamsung-ipc 1.0  | Improve package libsamsung-ipc for Parabola                            | _I3^<br>RELATIVIS<br>M       | 09/23/2022 05:53 PM | Telephony and mobile data | Not device specific, Unknown           |                       |
| 2293 | Upstreaming patches      | In Progress | Normal   | Infrastructure      | Redmine: fix crash when retrieving page with no author                 | _I3^<br>RELATIVIS<br>M       | 04/29/2024 10:02 PM | Redmine                   |  | Work not started      |
| 2292 | Replicant                | New         | Normal   | Replicant 6.0 0005  | How to hide the Caller ID?   |                              | 01/27/2022 01:20 PM |                           | Galaxy S 2 (I9100), Galaxy S 3 (I9300) |                       |
| 2291 | Replicant                | New         | Normal   | Replicant 6.0 0004  | Make sure that users use up to date signature verification keys        |                              | 12/14/2021 05:03 PM | Installation instructions | Not device specific                    |                       |
| 2290 | Replicant                | New         | Normal   | Replicant 6.0       | Investigate Waydroid as upstream                                       |                              | 12/11/2021 04:42 PM |                           | Not device specific                    |                       |
| 2289 | Replicant infrastructure | New         | Normal   |                     | Document the matterbridge package in Guix                              |                              | 12/07/2021 05:07 PM | Patch upstreaming         |  |                       |

| #    | Project                  | Status | Priority | Target version      | Subject   | Assignee | Updated             | Category     | Device  | Upstream patch status |
|------|--------------------------|--------|----------|---------------------|---|----------|---------------------|--------------|---|-----------------------|
| 2285 | Replicant                | New    | Normal   | Replicant 11.0 0001 | Recovery: stuck in the recovery after factory reset   |          | 11/17/2021 04:46 PM |              | Galaxy S 3 (I9300)  |                       |
| 2282 | Replicant                | New    | Normal   | Replicant 11.0 0001 | Switch the cache partition to F2FS  |          | 10/06/2021 03:49 PM | Build system | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)   |                       |
| 2280 | Upstreaming patches      | New    | Normal   | Replicant 11.0 0001 | Fix Heimdall bug #494 (Heimdall can flash files bigger than partitions)   |          | 12/07/2021 04:56 PM | Heimdall     |   | Work not started      |
| 2279 | Replicant                | New    | Normal   | Replicant 11.0 0001 | Fix suspend/resume?   |          | 09/18/2021 05:50 PM |              | Galaxy S 2 (I9100), Galaxy S 3 (I9300)  |                       |
| 2278 | Replicant                | New    | Normal   | Replicant 11.0 0002 | WiFi: create free software nvram data   |          | 09/18/2021 05:37 PM | Wi-Fi        | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)   |                       |
| 2277 | Replicant                | New    | Normal   | Replicant 11.0 0002 | Replicant WiFi HAL / macloader: Autodetect firmware paths   |          | 09/18/2021 05:30 PM | Wi-Fi        | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)   |                       |
| 2276 | Replicant                | New    | Normal   | Replicant 11.0 0002 | Replicant WiFi HAL: improve WiFi interface autodetection  |          | 09/18/2021 05:25 PM | Wi-Fi        | Not device specific   |                       |
| 2275 | Replicant                | New    | Normal   | Replicant 6.0       | Finish Ethernet support (relatively easy)   |          | 09/14/2021 02:25 PM | Build system | Galaxy Note 2 (GT-N7100), Galaxy Note 8.0 (N51xx), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx) |                       |
| 2274 | Replicant                | New    | Normal   | Replicant 11.0      | Enable to install Guix on Replicant 11  |          | 09/06/2021 01:37 PM | Build system | Not device specific   |                       |
| 2270 | Replicant                | New    | Normal   | Replicant 6.0       | usb_networking_device.sh DNS servers are down   |          | 08/23/2021 04:01 PM |              | Not device specific   |                       |
| 2269 | Replicant                | New    | Normal   | Any version         | Review android-rebuilds SDK for building Android applications   |          | 09/24/2024 10:06 AM | SDK          | Not device specific   |                       |
| 2268 | Replicant infrastructure | New    | Normal   |                     | Find how to generate git bundles to make Replicant source download faster   |          | 08/08/2021 11:27 PM |              |   |                       |
| 2267 | Upstreaming patches      | New    | Normal   | Replicant 11.0      | Upstream the workaround for the VTU00M 0xf1 FTL metadata corruption bug which affects (at least) the GT-I9300 and GT-N7100 eMMC |          | 04/29/2024 09:56 PM | Linux        |   | Work not started      |

| #    | Project                  | Status | Priority | Target version      | Subject  | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|--------------------------|--------|----------|---------------------|--|------------------------|---------------------|---------------------------|---|-----------------------|
| 2266 | Replicant                | New    | Normal   | Replicant 11.0 0001 | Integrate (belgin's?) liblight   | Denis 'GNUtoo' Carikli | 09/02/2021 11:07 AM | Build system              | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)         |                       |
| 2265 | Replicant                | New    | Normal   | Replicant 6.0       | Check if there is any lost memory for the Galaxy SII (GT-I9100)  |                        | 06/27/2021 03:46 PM | Devices                   | Galaxy S 2 (I9100)                                |                       |
| 2264 | Replicant                | New    | Normal   | Replicant 6.0       | Battery consumption issue on N7100   |                        | 12/27/2021 01:21 PM |                           | Galaxy Note 2 (GT-N7100), Unknown                 |                       |
| 2263 | Replicant                | New    | Normal   | Replicant 6.0       | ipc-modem --debug --call xxxxxxxxxx start works 1 time out of 2  |                        | 06/17/2021 03:05 PM | Telephony and mobile data | Galaxy S 3 (I9300)                                |                       |
| 2262 | Replicant                | New    | Normal   |                     | Investigate if <a href="http://deviceinfohw.ru/">http://deviceinfohw.ru/</a> is usable somehow   |                        | 06/06/2021 06:25 AM |                           |   |                       |
| 2260 | Replicant infrastructure | New    | Normal   |                     | Add and upstream support for matterbridge in Trisquel  |                        | 06/04/2021 03:35 PM | Patch upstreaming         |   |                       |
| 2257 | Replicant                | New    | Normal   | Replicant 6.0 0004  | Dialer crashing because of (contact?) database format  |                        | 06/01/2021 03:10 PM | Base applications         | Galaxy Note 2 (GT-N7100), Galaxy Note 8.0 (N51xx) |                       |
| 2254 | Replicant infrastructure | New    | Normal   |                     | OpenSMTPd key permission changes   |                        | 05/24/2021 01:26 PM |                           |   |                       |
| 2253 | Replicant infrastructure | New    | Normal   |                     | Multiple issues with certificates updates  |                        | 08/23/2021 05:40 PM |                           |   |                       |
| 2252 | Replicant                | New    | Normal   | Replicant 11.0 0001 | Evaluate <a href="https://github.com/phhusson/vendor_foss">https://github.com/phhusson/vendor_foss</a>                                       |                        | 05/10/2021 10:26 AM | Build system              | Not device specific                               |                       |
| 2251 | Replicant                | New    | Normal   | Replicant 11.0 0001 | Ship APK source code   |                        | 05/12/2021 10:46 PM | Build system              | Not device specific                               |                       |
| 2250 | Replicant                | New    | Normal   | Replicant 6.0       | Ship APK source code too   |                        | 05/06/2021 03:41 PM | Build system              | Not device specific                               |                       |
| 2249 | Replicant                | New    | Normal   | Replicant 6.0       | Investigate Exynos 4412 GPJ0(1) GPIO on the Galaxy SIII (GT-I9300)   |                        | 05/05/2021 02:01 PM | Telephony and mobile data | Galaxy S 3 (I9300)                                |                       |
| 2248 | Replicant                | New    | Normal   | Any version         | Enable more easy updating of release keys  |                        | 05/03/2021 04:05 PM |                           | Not device specific                               |                       |
| 2247 | Replicant                | New    | Normal   | Replicant 6.0 0005  | Update gen_key_migration_script README to take into account the changes between replicant-6.0-0004-rc5 and replicant-6.0-0004-rc5-transition |                        | 05/03/2021 04:16 PM |                           | Not device specific                               |                       |

| #    | Project   | Status | Priority | Target version      | Subject  | Assignee               | Updated             | Category                 | Device   | Upstream patch status |
|------|-----------|--------|----------|---------------------|--|------------------------|---------------------|--------------------------|--|-----------------------|
| 2246 | Replicant | New    | Normal   | Replicant 6.0 0004  | Test the RC5 on the supported devices  |                        | 05/03/2021 03:49 PM |                          | Galaxy Nexus (GT-I9250), Galaxy Note (GT-N7000), Galaxy Note 2 (GT-N7100), Galaxy Note 8.0 (N51xx), Galaxy S (I9000), Galaxy S 2 (I9100), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx) |                       |
| 2245 | Replicant | New    | Normal   | Any version         | Separate the gpg keys from the releases  | Denis 'GNUtoo' Carikli | 04/29/2021 09:45 AM |                          | Not device specific  |                       |
| 2244 | Replicant | New    | Normal   | Replicant 11.0      | Investigate the tradeoffs of scudo vs gmalloc                                      |                        | 04/26/2021 10:07 PM |                          | Unknown  |                       |
| 2243 | Replicant | New    | Normal   | Replicant 11.0 0001 | Cannot encrypt the phone because it doesn't recognize the battery is fully charged |                        | 03/28/2021 01:53 PM |                          | Galaxy S 3 4G (I9305)  |                       |
| 2242 | Replicant | New    | Normal   | Replicant 11.0      | Investigate the option to choose between GPU drivers under the "Developer options" |                        | 03/28/2021 01:44 PM |                          | Not device specific  |                       |
| 2241 | Replicant | New    | Normal   | Replicant 11.0 0001 | Ship a terminal application or document how to use the builtin one                 |                        | 01/01/2023 06:01 PM |                          | Not device specific  |                       |
| 2240 | Replicant | New    | Normal   | Replicant 11.0 0001 | Recovery: "Power off" reboots  |                        | 03/28/2021 01:33 PM | Recovery                 | Galaxy S 3 4G (I9305)  |                       |
| 2239 | Replicant | New    | Normal   | Replicant 11.0 0001 | Recovery: "Failed to clear BCB message: failed to find /misc partition"            |                        | 03/28/2021 01:29 PM | Recovery                 | Galaxy S 3 4G (I9305)  |                       |
| 2238 | Replicant | New    | Normal   |                     | Document the "Type of work" in a wiki page + also point to how to find bug reports |                        | 03/27/2021 04:20 PM | Website and wiki content | Not device specific  |                       |
| 2237 | Replicant | New    | Normal   | Replicant 9.0       | Investigate and/or document Replicant 9 graphics speed                             | dl lud                 | 03/27/2021 03:44 PM | Graphics                 | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)  |                       |
| 2236 | Replicant | New    | Normal   | Replicant 11.0 0001 | Test automatic suspend and fix it if it's broken                                   |                        | 03/25/2021 12:53 PM |                          | Unknown  |                       |
| 2235 | Replicant | New    | Normal   | Replicant 11.0 0001 | fix userdata.img flashing  |                        | 03/23/2021 11:36 PM | Build system             | Not device specific  |                       |

| #    | Project   | Status | Priority | Target version      | Subject   | Assignee               | Updated             | Category                  | Device                      | Upstream patch status |
|------|-----------|--------|----------|---------------------|---|------------------------|---------------------|---------------------------|-----------------------------|-----------------------|
| 2233 | Replicant | New    | Normal   | Replicant 11.0 0001 | Integrate rild in the HIDL / Manifest   | Denis 'GNUtoo' Carikli | 03/14/2021 10:32 PM | Telephony and mobile data | Galaxy S 3 (I9300)          |                       |
| 2232 | Replicant | New    | Normal   | Replicant 11.0 0001 | Check if the EFS works fine   | Denis 'GNUtoo' Carikli | 04/04/2022 12:56 PM | Telephony and mobile data | Galaxy S 3 (I9300), Unknown |                       |
| 2230 | Replicant | New    | Normal   | Replicant 6.0 0004  | Write a procedure (in english or shell) to migrate the contacts   |                        | 05/03/2021 04:16 PM | Website and wiki content  | Not device specific         |                       |
| 2229 | Replicant | New    | Normal   | Replicant 6.0 0004  | /data/system/applications.xml corruption at boot ?  |                        | 04/26/2021 10:19 AM | Build system              | Not device specific         |                       |
| 2228 | Replicant | New    | Normal   |                     | Categorize bugs in the bug tracker to enable contributors to find things they want to work on   |                        | 03/07/2021 11:42 AM |                           | Unknown                     |                       |
| 2227 | Replicant | New    | Normal   |                     | Fix device names in the "Device" field in redmine Issues / bug reports  |                        | 03/07/2021 11:35 AM | Website and wiki content  | Unknown                     |                       |
| 2226 | Replicant | New    | Normal   | Replicant 6.0 0004  | Remove remaining nonfree firmwares in kernel_samsung_smdk4412 in Replicant 6  |                        | 03/11/2021 05:10 PM | Freedom                   | Unknown                     |                       |
| 2224 | Replicant | New    | Normal   | Any version         | Ship sources tarball along with the images and verify if we can fetch all the releases at the time  |                        | 03/07/2021 05:24 PM | Legal                     | Not device specific         |                       |
| 2223 | Replicant | New    | Normal   | Replicant 6.0       | Lost phone modem connectivity   |                        | 02/25/2021 07:13 PM |                           | Galaxy S 3 (I9300)          |                       |
| 2222 | Replicant | New    | Normal   | libsamsung-ipc 1.0  | Better logging system   |                        | 03/07/2021 11:43 AM | Telephony and mobile data | Not device specific         |                       |
| 2221 | Replicant | New    | Normal   | libsamsung-ipc 1.0  | Support at least one generic use case   |                        | 03/07/2021 11:46 AM | Telephony and mobile data | Unknown                     |                       |
| 2220 | Replicant | New    | Normal   | libsamsung-ipc 1.0  | Pass the client struct to all public functions  |                        | 03/07/2021 11:54 AM | Telephony and mobile data | Unknown                     |                       |
| 2219 | Replicant | New    | Normal   | libsamsung-ipc 1.0  | standardize devices's .poll()   |                        | 03/29/2021 04:06 PM | Telephony and mobile data | Unknown                     |                       |
| 2218 | Replicant | New    | Normal   | Replicant 11.0      | Investigate how to push modem firmware loading + on/off in the kernel   |                        | 03/26/2021 09:09 PM | Telephony and mobile data | Unknown                     |                       |
| 2216 | Replicant | New    | Normal   | Any version         | Promote an SDK for writing Android applications   |                        | 03/26/2021 09:05 PM |                           | Unknown                     |                       |
| 2214 | Replicant | New    | Normal   |                     | Document <a href="https://blog.korena.xyz/embedded-arm-cortex-a7/">https://blog.korena.xyz/embedded-arm-cortex-a7/</a> and <a href="https://github.com/korena/S5PV210-bootloader">https://github.com/korena/S5PV210-bootloader</a> + check licenses |                        | 03/26/2021 09:03 PM | Bootloaders               | Unknown                     |                       |
| 2213 | Replicant | New    | Normal   | Replicant 6.0       | document debian bug about repo updating itself ( <a href="https://bugs.debian.org/cgi-bin/bugreport.cgi?bug=%23855846">https://bugs.debian.org/cgi-bin/bugreport.cgi?bug=%23855846</a> )  |                        | 05/18/2021 04:33 PM | Website and wiki content  | Unknown                     |                       |
| 2212 | Replicant | New    | Normal   | Replicant 6.0       | ReleaseKey#Retrieving-the-Replicant-release-key: outdated <a href="https://riseup.net/en/security/message-security/openpgp/best-practices">https://riseup.net/en/security/message-security/openpgp/best-practices</a> link                          |                        | 03/26/2021 09:01 PM | Installation instructions | Unknown                     |                       |



| #    | Project                  | Status | Priority | Target version                                | Subject   | Assignee               | Updated             | Category                  | Device   | Upstream patch status |
|------|--------------------------|--------|----------|---|---|------------------------|---------------------|---------------------------|--|-----------------------|
| 2211 | Replicant                | New    | Normal   | Replicant 11.0 0001                           | Check reboot driver   | Denis 'GNUtoo' Carikli | 03/26/2021 09:01 PM |                           | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305) |                       |
| 2210 | Replicant infrastructure | New    | Normal   |   | Mastodon instance: Translate Terms of services  |                        | 08/08/2021 11:25 PM |                           |  |                       |
| 2209 | Replicant                | New    | Normal   | Replicant 6.0                                 | Add infos about chromium issues in debian + jami ( <a href="https://bugs.debian.org/972134">https://bugs.debian.org/972134</a> ) in the wiki somewhere  |                        | 03/26/2021 09:00 PM |                           | Unknown  |                       |
| 2208 | Replicant                | New    | Low      | Replicant 6.0                                 | Improve logos/theming on the bottom of mailing list web interface   | _I3^ RELATIVIS M       | 03/26/2021 08:59 PM |                           | Not device specific, Unknown   |                       |
| 2206 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Note 2 LTE modem on mainline kernel   |                        | 01/04/2024 12:32 AM |                           | New device   |                       |
| 2204 | Replicant                | New    | Normal   | Replicant 6.0                                 | Look at <a href="https://github.com/comsecuris/shannonRE">https://github.com/comsecuris/shannonRE</a> (low level Modem info on the Galaxy S6)   |                        | 03/26/2021 08:58 PM |                           | Unknown  |                       |
| 2203 | Replicant                | New    | Normal   | Replicant 6.0                                 | Host <a href="http://www.replicant.us">www.replicant.us</a>   |                        | 03/07/2021 11:53 AM | Infrastructure (web, git) | Not device specific  |                       |
| 2202 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | midas: Make usb host work   |                        | 04/29/2024 09:57 PM | Linux                     |  | Work not started      |
| 2201 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | look into <a href="https://www.xda-developers.com/samsung-galaxy-s-ii-unofficial-android-11-lineageos-18-1">https://www.xda-developers.com/samsung-galaxy-s-ii-unofficial-android-11-lineageos-18-1</a> |                        | 03/26/2021 08:57 PM |                           | Unknown  |                       |
| 2200 | Replicant                | New    | Normal   | Replicant 6.0                                 | Check if there are incompatible Galaxy SII partition schemes  |                        | 03/26/2021 08:56 PM | Build system              | Galaxy S 2 (I9100)   |                       |
| 2199 | Replicant                | New    | Normal   | Replicant 6.0                                 | repo 2.10 stops working in debian 9.13 (stretch)  | Denis 'GNUtoo' Carikli | 03/26/2021 08:55 PM |                           | Unknown  |                       |
| 2198 | Replicant                | New    | Normal   | Replicant 6.0                                 | GDPR: look at <a href="https://osmocom.org/projects/cellular-infrastructure/wiki/Privacy_Policy">https://osmocom.org/projects/cellular-infrastructure/wiki/Privacy_Policy</a>                           |                        | 03/26/2021 08:54 PM |                           | Unknown  |                       |
| 2195 | Replicant                | New    | Normal   | Replicant 11.0 0001                           | Build the kernel in Replicant 11 sources  |                        | 03/26/2021 08:49 PM | Build system              | Unknown  |                       |
| 2192 | Replicant                | New    | Normal   | Replicant 6.0                                 | Document how easy it is to change the battery of one of the supported tablets.  |                        | 03/26/2021 08:46 PM | Website and wiki content  | Unknown  |                       |

| #    | Project                  | Status | Priority | Target version                                | Subject  | Assignee | Updated             | Category                 | Device                                    | Upstream patch status |
|------|--------------------------|--------|----------|---|--|----------|---------------------|--------------------------|---|-----------------------|
| 2191 | Replicant                | New    | Normal   | Replicant 6.0                                 | BackupTheDataPartition: warn about 'adb: error: cannot stat 'USERDATA.img': Value too large for defined data type' |          | 03/26/2021 08:46 PM |                          | Unknown                                   |                       |
| 2190 | Replicant                | New    | Normal   | Any version                                   | Ask the FSF if they can also accept Litecoin donations on our behalf   |          | 03/26/2021 08:43 PM | Website and wiki content | Not device specific                       |                       |
| 2189 | Replicant                | New    | Normal   | Replicant 6.0                                 | Document patches for the p4note  |          | 03/26/2021 08:42 PM |                          | Unknown                                   |                       |
| 2187 | Replicant                | New    | Normal   | Replicant 11.0 0001                           | make adb shell work without sudo   |          | 03/26/2021 08:38 PM |                          | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305) |                       |
| 2186 | Replicant                | New    | Normal   | Replicant 11.0                                | Add Support for the Samsung XCover 2 - GT-S7710  |          | 03/26/2021 08:37 PM | Devices                  | Unknown                                   |                       |
| 2185 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Add support for the Samsung Galaxy S III mini (GT-i8190)   |          | 03/26/2021 08:36 PM | Devices                  | New device                                |                       |
| 2184 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | midas: check which exynos we have  |          | 03/26/2021 08:35 PM | Bootloaders              | Unknown                                   |                       |
| 2183 | Replicant                | New    | Normal   | Replicant 6.0                                 | Exynos4412: look if there are unfused boards   |          | 03/26/2021 08:34 PM | Bootloaders              | Unknown                                   |                       |
| 2182 | Replicant infrastructure | New    | Normal   |   | Replicant mirroring system: develop a script that generates redirects  |          | 03/26/2021 08:33 PM |                          |   |                       |
| 2181 | Replicant                | New    | Normal   |   | Document GT-I9300 JTAG pads  |          | 03/26/2021 08:31 PM | Website and wiki content | Galaxy S 3 (I9300)                        |                       |
| 2180 | Replicant                | New    | Normal   | replicant 10.0                                | cleanup source   |          | 03/26/2021 08:31 PM |                          | Unknown                                   |                       |
| 2177 | Upstreaming patches      | New    | Normal   | Replicant 11.0 0001                           | Cleanup midas reboot patch   |          | 09/21/2021 02:08 PM | Linux                    |   | Work not started      |
| 2176 | Replicant                | New    | Normal   | Replicant 11.0 0001                           | Check if the cable detection is reliable   |          | 03/26/2021 08:28 PM |                          | Unknown                                   |                       |
| 2175 | Replicant                | New    | Normal   | Any version                                   | Find a Galaxy Tab 2 breakout board for the vendor-specific connector   |          | 03/26/2021 08:27 PM | Website and wiki content | Unknown                                   |                       |
| 2174 | Replicant                | New    | Normal   |   | Replicant >= 11: look how seedvault can be used  |          | 03/26/2021 08:26 PM |                          | Unknown                                   |                       |
| 2173 | Replicant infrastructure | New    | Normal   |   | Setup onion services   |          | 03/26/2021 08:24 PM |                          |   |                       |

| #    | Project   | Status | Priority | Target version                                | Subject   | Assignee | Updated             | Category                 | Device   | Upstream patch status |
|------|-----------|--------|----------|---|---|----------|---------------------|--------------------------|--|-----------------------|
| 2172 | Replicant | New    | Normal   | Any Replicant version with an upstream kernel | porting guide/documentation: warn about selinux not handling symlinks   |          | 03/26/2021 08:23 PM |                          | Unknown  |                       |
| 2171 | Replicant | New    | Normal   | Replicant 6.0 0005                            | OMAP device: very slow llvmpipe   |          | 02/27/2021 08:39 AM |                          | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx) |                       |
| 2167 | Replicant | New    | Normal   | Replicant 6.0                                 | PortADeviceToLinux: See if we need to move "Keeping the device in a good state" in a more generic page                                  |          | 03/29/2021 04:04 PM | Website and wiki content | Not device specific  |                       |
| 2166 | Replicant | New    | Normal   | Replicant 6.0                                 | Create wiki portal for using Replicant  |          | 03/29/2021 04:03 PM | Website and wiki content | Unknown  |                       |
| 2164 | Replicant | New    | Normal   | Replicant 6.0 0004                            | Finish [[ApplicationsSecurityModel]]  |          | 03/29/2021 04:01 PM | Website and wiki content | Not device specific  |                       |
| 2163 | Replicant | New    | Normal   | Replicant 6.0 0004                            | Finish [[DataPartition]]  |          | 03/29/2021 03:59 PM | Website and wiki content | Unknown  |                       |
| 2162 | Replicant | New    | Normal   | Replicant 6.0 0004                            | Finish [[BackupTheDataPartition]]   |          | 03/26/2021 08:13 PM | Website and wiki content | Unknown  |                       |
| 2161 | Replicant | New    | Normal   | Replicant 6.0 0004                            | Finish [[RestoreApplicationInternalData]]   |          | 03/26/2021 08:12 PM | Website and wiki content | Unknown  |                       |
| 2159 | Replicant | New    | Normal   | Any version                                   | document the Galaxy Tab 2 available bootloaders   |          | 03/26/2021 08:10 PM | Website and wiki content | Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx), Unknown                                       |                       |
| 2158 | Replicant | New    | Normal   | Replicant 6.0                                 | Replicant releases: Publish ramdisk.img and zimages as well to enable people to make custom images (for instance with root) more easily |          | 11/05/2020 03:35 PM |                          | Unknown  |                       |
| 2157 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Add charging mode at poweroff when a cable is plugged   |          | 03/26/2021 08:08 PM |                          | Unknown  |                       |
| 2156 | Replicant | New    | Normal   | Replicant 6.0 0005                            | release-script: build: detect if the builder is online or offline   |          | 05/03/2021 04:15 PM | Build system             | Not device specific  |                       |
| 2155 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Make sure that we mirrors all repos, even with manual redirects   |          | 03/26/2021 08:03 PM |                          | Unknown  |                       |
| 2154 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Handle suspend/resume (check if it works fine) and decent battery life  |          | 03/26/2021 08:03 PM |                          | Unknown  |                       |

| #    | Project                  | Status      | Priority | Target version                                | Subject   | Assignee               | Updated             | Category                  | Device   | Upstream patch status |
|------|--------------------------|-------------|----------|---|---|------------------------|---------------------|---------------------------|--|-----------------------|
| 2153 | Replicant                | New         | Normal   | Replicant 11.0 0001                           | Enable users to get root directly on the device   |                        | 05/18/2021 08:35 PM |                           | Unknown  |                       |
| 2151 | Replicant                | New         | Normal   | Replicant 11.0 0001                           | Make adb shell work out of the box  |                        | 03/26/2021 07:59 PM |                           | Unknown  |                       |
| 2150 | Replicant                | New         | Normal   | Any version                                   | libsamsung-ipc: improve board drivers print   |                        | 03/26/2021 07:57 PM | Telephony and mobile data | Unknown  |                       |
| 2149 | Replicant                | New         | Normal   | Replicant 6.0                                 | Explain what is a bootloader in the context of smartphones/tablets and explain what is a recovery image |                        | 03/26/2021 07:57 PM | Installation instructions | Unknown  |                       |
| 2148 | Replicant                | In Progress | Normal   | Any Replicant version with an upstream kernel | Test Trisquel 9 for building Replicant  |                        | 09/03/2021 10:21 PM | Build system              | Galaxy Nexus (GT-I9250), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx) |                       |
| 2147 | Replicant                | New         | Normal   | Replicant 11.0 0002                           | Enable accelerometers   |                        | 03/26/2021 07:56 PM |                           | Unknown  |                       |
| 2146 | Replicant                | New         | Normal   | Replicant 11.0 0002                           | Graphics rotation issue?  |                        | 03/26/2021 07:56 PM | Graphics                  | Unknown  |                       |
| 2145 | Replicant                | New         | Normal   | Replicant 11.0 0001                           | Remove phone number lookup again in replicant 10  |                        | 03/26/2021 07:55 PM |                           | Unknown  |                       |
| 2144 | Replicant                | New         | Normal   | Replicant 11.0 0001                           | Make the vibrator work  |                        | 03/26/2021 07:55 PM |                           | Unknown  |                       |
| 2143 | Upstreaming patches      | New         | Normal   | Replicant 11.0                                | Create and upstream a dts for the I9100G  |                        | 04/29/2024 09:59 PM | Linux                     |  | Work not started      |
| 2142 | Replicant                | New         | Normal   | Replicant 6.0 0005                            | investigate out/target/product/i9300/recovery.img out/dist/i9300/recovery-i9300.img differences         |                        | 03/26/2021 07:50 PM |                           | Unknown  |                       |
| 2141 | Replicant                | New         | Normal   | Replicant 11.0 0001                           | Enable reboot to recovery and reboot to bootloader  |                        | 03/26/2022 11:43 PM |                           | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Unknown                           |                       |
| 2140 | Replicant infrastructure | New         | Normal   |   | Add server with limited public IRC logs   | Denis 'GNUtoo' Carikli | 03/26/2021 07:38 PM |                           |  |                       |
| 2139 | Replicant infrastructure | New         | Normal   | Replicant 11.0 0002                           | Handle redirects for git in a clean way for AOSP  |                        | 03/26/2021 07:37 PM |                           |  |                       |
| 2138 | Replicant                | New         | Normal   | Replicant 6.0                                 | Add P5100 to the EFS backup instructions  |                        | 03/26/2021 07:37 PM | Installation instructions | Galaxy Tab 2 10.1 (P51xx)  |                       |
| 2137 | Replicant                | New         | Normal   | Replicant 6.0                                 | Portable Wi-Fi hotspot  |                        | 03/26/2021 07:35 PM |                           | Unknown  |                       |

| #    | Project   | Status | Priority | Target version      | Subject   | Assignee               | Updated             | Category                  | Device   | Upstream patch status |
|------|-----------|--------|----------|---------------------|---|------------------------|---------------------|---------------------------|--|-----------------------|
| 2135 | Replicant | New    | Normal   | Replicant 6.0       | Warn about mutiple similar commands sections  |                        | 03/29/2021 03:53 PM | Installation instructions | Unknown  |                       |
| 2134 | Replicant | New    | Normal   | Replicant 6.0       | Generate installation instructions  |                        | 03/26/2021 07:31 PM | Installation instructions | Unknown  |                       |
| 2133 | Replicant | New    | Normal   | Replicant 6.0       | install through USB key links to adb  |                        | 03/29/2021 03:53 PM | Installation instructions | Unknown  |                       |
| 2132 | Replicant | New    | Normal   | Replicant 6.0       | One of the page has "installation or s." which looks unfinished   |                        | 03/26/2021 07:29 PM | Installation instructions | Unknown  |                       |
| 2130 | Replicant | New    | Normal   | Replicant 6.0       | installation instructions pages: add examples for <path/to> to clarify the instructions   |                        | 03/26/2021 07:28 PM | Installation instructions | Unknown  |                       |
| 2129 | Replicant | New    | Normal   | Replicant 6.0       | [[RecoveryInstallationWithHeimdal]] and other installation pages: add examples for <yourdevice> to clarify the instructions   |                        | 03/26/2021 07:28 PM | Installation instructions | Unknown  |                       |
| 2128 | Replicant | New    | Normal   | Replicant 6.0       | For all maintained devices: Update the link to the installation instructions to point to the installation section in the main page  |                        | 03/26/2021 07:27 PM | Installation instructions | Unknown  |                       |
| 2126 | Replicant | New    | Normal   | libsamsung-ipc 1.0  | Fix duplicated board_name in libsamsung-ipc   |                        | 04/04/2022 12:53 PM | Telephony and mobile data | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy Note 8.0 (N51xx), Galaxy S 3 (I9300) |                       |
| 2125 | Replicant | New    | Normal   | Replicant 11.0 0001 | Report battery % / charging   |                        | 09/28/2021 01:27 PM |                           | Galaxy S 3 (I9300), Unknown  |                       |
| 2124 | Replicant | New    | Normal   | Replicant 6.0       | Replicant installation for Galaxy Nexus (GT-I9250)  |                        | 03/26/2021 07:24 PM | Installation instructions | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250)  |                       |
| 2123 | Replicant | New    | Normal   |                     | link to <a href="https://eighty-twenty.org/2020/09/10/booting-samsung-galaxy-s7-modem-in-the-wiki">https://eighty-twenty.org/2020/09/10/booting-samsung-galaxy-s7-modem-in-the-wiki</a> |                        | 03/26/2021 07:23 PM | Telephony and mobile data | Unknown  |                       |
| 2120 | Replicant | New    | Normal   | Any version         | Research FLAG_HARDWARE_ACCELERATED in frameworks/base/core/java/android/content/pm/ApplicationInfo.java   |                        | 03/26/2021 07:22 PM | Graphics                  | Unknown  |                       |
| 2119 | Replicant | New    | Normal   | Replicant 11.0 0001 | Add support for the Replicant 11 kernel modem driver in libsamsung-ipc, possibly in a replicant-11 branch   | Denis 'GNUtoo' Carikli | 03/26/2021 07:22 PM |                           | Galaxy S 3 (I9300)   |                       |
| 2118 | Replicant | New    | Normal   | Replicant 11.0 0001 | Finish cleaning up the Linux modem driver, fix bugs, and import it in the Replicant 11 kernel   | Denis 'GNUtoo' Carikli | 03/26/2021 07:21 PM |                           | Galaxy S 3 (I9300)   |                       |

| #    | Project   | Status | Priority | Target version                                | Subject  | Assignee               | Updated             | Category                  | Device   | Upstream patch status |
|------|-----------|--------|----------|---|--|------------------------|---------------------|---------------------------|--|-----------------------|
| 2117 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Add SRS support in Replicant 11  | Denis 'GNUtoo' Carikli | 03/26/2021 07:18 PM |                           | Galaxy S 3 (I9300)   |                       |
| 2116 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Add support for the Replicant 11 kernel in libsamsung-ipc  | Denis 'GNUtoo' Carikli | 03/26/2021 07:18 PM |                           | Galaxy S 3 (I9300)   |                       |
| 2115 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Port libsamsung-ril to Replicant 11  | Denis 'GNUtoo' Carikli | 03/26/2021 07:17 PM |                           | Galaxy S 3 (I9300)   |                       |
| 2114 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Create a recovery  | Denis 'GNUtoo' Carikli | 09/18/2021 05:46 PM |                           | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)  |                       |
| 2113 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Create installation instructions   | Denis 'GNUtoo' Carikli | 03/26/2021 07:14 PM |                           | Unknown  |                       |
| 2112 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Find and remove privacy issues   | Denis 'GNUtoo' Carikli | 08/24/2020 10:35 PM |                           | Unknown  |                       |
| 2111 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Find the software licenses and remove nonfree software   | Denis 'GNUtoo' Carikli | 11/21/2021 02:34 AM |                           | Not device specific  |                       |
| 2110 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Minimal Replicant branding, was: Rebrand as Replicant  | Denis 'GNUtoo' Carikli | 11/25/2021 01:23 PM |                           | Unknown  |                       |
| 2108 | Replicant | New    | Normal   | Replicant 11.0 0001                           | Make audio work  | Denis 'GNUtoo' Carikli | 11/12/2021 11:40 PM |                           | Unknown  |                       |
| 2107 | Replicant | New    | Normal   | Replicant 11.0 0002                           | Make sensor libraries work   | Denis 'GNUtoo' Carikli | 03/29/2021 03:48 PM |                           | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)  |                       |
| 2105 | Replicant | New    | Normal   | Any Replicant version with an upstream kernel | Investigate custom kernels for fixes or improvements on: audio, frequency and voltage scalling, display control and others |                        | 03/26/2021 07:00 PM |                           | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305) |                       |
| 2102 | Replicant | New    | Normal   | Replicant 6.0                                 | Replicant does not properly recognise a SIM card from a German internet provider   |                        | 06/11/2022 10:49 AM | SIM card not recognized   | Galaxy S 3 (I9300)   |                       |
| 2101 | Replicant | New    | Normal   |   | Document/implement the Replicant way of SIM unlock   |                        | 03/26/2021 06:47 PM | Telephony and mobile data | Unknown  |                       |

| #    | Project                  | Status | Priority | Target version                                | Subject   | Assignee | Updated             | Category                                 | Device   | Upstream patch status |
|------|--------------------------|--------|----------|---|---|----------|---------------------|--|--|-----------------------|
| 2100 | Replicant                | New    | Normal   | Any version                                   | Document EFS v1 and EFS v2 differences  |          | 03/26/2021 06:45 PM | Telephony and mobile data                | Galaxy S 3 (I9300)                                 |                       |
| 2099 | Replicant                | New    | Normal   | replicant 10.0                                | Separate screen lock and boot passwords   |          | 03/26/2021 06:44 PM | Security                                 | Not device specific                                |                       |
| 2098 | Replicant                | New    | Normal   | Any version                                   | Support SIM network unlock  |          | 07/30/2020 08:29 PM | Telephony and mobile data                | Unknown  |                       |
| 2097 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Check if mainline Linux has blobs for our targets   |          | 03/26/2021 06:39 PM | Upstream antifeatures and privacy issues | Unknown  |                       |
| 2096 | Replicant                | New    | Low      |   | Do a security analysis of the factory resets mode and improve it  |          | 07/22/2020 11:58 PM |  | Unknown  |                       |
| 2095 | Replicant                | New    | Low      |   | Identify unknown data after the PIT in the Galaxy SIII (GT-I9300, GT-I9305)   |          | 07/22/2020 11:32 PM |  | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Unknown |                       |
| 2094 | Replicant                | New    | Normal   | Any version                                   | Make xgoldmon work with other devices than the Galaxy Nexus   |          | 12/31/2020 03:05 AM |  | Unknown  |                       |
| 2093 | Replicant                | New    | Normal   |   | Document advocacy about the radio directive and similar laws/reglements   |          | 03/26/2021 06:31 PM | Website and wiki content                 | Unknown  |                       |
| 2092 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Evaluate <a href="https://bootlin.com/doc/legacy/android/">https://bootlin.com/doc/legacy/android/</a> for a guide to contribute to Replicant |          | 03/26/2021 06:31 PM | Website and wiki content                 | Unknown  |                       |
| 2091 | Replicant                | New    | Normal   |   | read <a href="#">how-to-lock-the-samsung-download-mode-using-an-undocumented-feature-of-aboot</a> and integrate it in the wiki                |          | 03/26/2021 06:30 PM | Website and wiki content                 | Unknown  |                       |
| 2090 | Replicant infrastructure | New    | Normal   |   | Meta bug about discriminations and abuses   |          | 12/30/2020 12:42 AM |  |  |                       |
| 2089 | Replicant infrastructure | New    | Normal   |   | Forums require Javascript   |          | 03/26/2021 06:29 PM |  |  |                       |
| 2088 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Make u-boot midas work as boot.img  |          | 12/27/2020 08:09 PM | Bootloaders                              | Unknown  |                       |
| 2087 | Replicant                | New    | Normal   |   | Add GT-N5100 to [[Exynos4Bootrom]]  |          | 03/26/2021 06:28 PM | Website and wiki content                 | Unknown  |                       |
| 2085 | Replicant                | New    | Normal   |   | Document full backups and RPMB  |          | 03/26/2021 06:27 PM |  | Unknown  |                       |

| #    | Project                  | Status | Priority | Target version                                | Subject   | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|--------------------------|--------|----------|---|---|------------------------|---------------------|---------------------------|---|-----------------------|
| 2084 | Replicant                | New    | Normal   |   | Document the privacy and security implication of the modem protocol (GPIOs, HSIC link reset) for Replicant 10 |                        | 03/26/2021 06:27 PM |                           | Galaxy S 3 (I9300), Unknown                                 |                       |
| 2083 | Replicant                | New    | Normal   |   | Research factory reset security for Replicant 10  |                        | 07/11/2020 11:11 PM |                           | Unknown   |                       |
| 2081 | Replicant                | New    | Normal   | Any version                                   | Research information and counter measures to Cellbrite or similar devices                                     |                        | 03/26/2021 06:25 PM |                           | Unknown   |                       |
| 2080 | Replicant                | New    | Normal   | Replicant 11.0 0002                           | Make sure we detail the security model of Replicant (10) properly   | Denis 'GNUtoo' Carikli | 03/13/2021 09:14 PM | Website and wiki content  | Galaxy S 2 (I9100), Galaxy S 3 (I9300), Not device specific |                       |
| 2079 | Replicant                | New    | Normal   |   | Upload GT-I9300 top PCB picture to Archive.org and add it to [[DevicesPictures]]                              | Denis 'GNUtoo' Carikli | 03/26/2021 06:20 PM | Website and wiki content  | Galaxy S 3 (I9300)  |                       |
| 2078 | Replicant                | New    | Normal   | Any version                                   | Add N7100 to [[Exynos4Bootrom]]   | Denis 'GNUtoo' Carikli | 03/26/2021 06:19 PM | Website and wiki content  | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100)             |                       |
| 2077 | Replicant                | New    | Normal   | Any version                                   | Document Galxy Note II (GT-N7100) JTAG pads   |                        | 03/26/2021 06:12 PM | Website and wiki content  | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100)             |                       |
| 2076 | Replicant                | New    | Normal   |   | Investigate I9300 eMMC toolbox  |                        | 07/15/2020 06:54 AM |                           | Galaxy Note 8.0 (N51xx)                                     |                       |
| 2073 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | PIT file editor: extend Heimdall with reverse of print-pit or create separate tool                            |                        | 04/29/2024 09:59 PM | Heimdall                  |   | Work not started      |
| 2072 | Replicant                | New    | Low      | Replicant 6.0                                 | Investigate how the stock RIL recovers partially corrupted EFS on GT-I9300                                    |                        | 03/26/2021 06:05 PM | Telephony and mobile data | Galaxy S 3 (I9300)  |                       |
| 2071 | Replicant infrastructure | New    | Normal   |   | Document how to publish blog posts  | Denis 'GNUtoo' Carikli | 03/26/2021 05:57 PM |                           |   |                       |
| 2070 | Replicant                | New    | Normal   |   | Mention gpg complexity in [[ReleasesKey]]   |                        | 03/26/2021 05:56 PM | Website and wiki content  | Unknown   |                       |
| 2067 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Document the Samsung Galaxy Camera  |                        | 03/26/2021 05:49 PM |                           | New device  |                       |
| 2066 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Document the Samsung Galaxy Camera 2  |                        | 03/26/2021 05:48 PM |                           | New device  |                       |



| #    | Project                  | Status | Priority | Target version                                | Subject   | Assignee               | Updated             | Category                  | Device  | Upstream patch status    |
|------|--------------------------|--------|----------|---|---|------------------------|---------------------|---------------------------|---------|--------------------------|
| 2064 | Replicant                | New    | Normal   | Replicant 9.0                                 | Make sure it can be fetched using the LineageOS mirror and sync with replicant-10   |                        | 03/26/2021 06:00 PM |                           | Unknown |                          |
| 2062 | Replicant infrastructure | New    | Normal   |   | Make git fsck work  |                        | 03/26/2021 05:45 PM |                           |         |                          |
| 2061 | Replicant infrastructure | New    | Normal   |   | Do git snapshots to protect mirror branches against upstream changing revision or rewriting history                               |                        | 06/26/2020 06:45 PM |                           |         |                          |
| 2060 | Replicant                | New    | Normal   |   | Add infos about signature check bypass through USB for recent exynos  |                        | 03/26/2021 05:41 PM | Website and wiki content  | Unknown |                          |
| 2059 | Replicant                | New    | Normal   | Any Replicant version with an upstream kernel | Add support for device(s) with dual sims?   |                        | 03/26/2021 05:38 PM |                           | Unknown |                          |
| 2058 | Replicant infrastructure | New    | Normal   |   | Ask the FSF to open port 993  |                        | 03/26/2021 05:37 PM |                           |         |                          |
| 2057 | Replicant                | New    | Normal   | Replicant 6.0                                 | Improve links to supported devices Was: Can I install replicant on a Galaxy a10e?   |                        | 03/26/2021 05:36 PM |                           | Unknown |                          |
| 2055 | Replicant infrastructure | New    | Normal   |   | Users need to run doveadm but config file might be absent   |                        | 03/29/2021 03:47 PM |                           |         |                          |
| 2053 | Replicant                | New    | Normal   | Replicant 6.0                                 | Document GPIO switch usage in <a href="https://github.com/okias/linux/tree/p4wifi">https://github.com/okias/linux/tree/p4wifi</a> |                        | 03/26/2021 05:29 PM |                           | Unknown |                          |
| 2052 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | Add libsamsung-ipc support in ofono   |                        | 04/29/2024 09:59 PM | oFono                     |         | Need to send a new serie |
| 2050 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | Upstream support for the Midas, Fix the Odroid U-3, and make sure it works in the kernel partition                                | Denis 'GNUtoo' Carikli | 04/29/2024 09:59 PM | U-boot                    |         | Patches review started   |
| 2049 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | Upstream "drm/panel: samsung: s6e8aa0: Add backlight control support"   | Joonas Kylmälä         | 04/29/2024 09:58 PM | Linux                     |         | Patches review started   |
| 2046 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | upstream "power_supply: max77693: Listen for cable events and enable charging"  |                        | 04/29/2024 09:58 PM | Linux                     |         | No response upstream     |
| 2045 | Upstreaming patches      | New    | Normal   | Replicant 11.0                                | upstream "mfd: max77693: Add defines for charger current control "  |                        | 04/29/2024 09:58 PM | Linux                     |         | No response upstream     |
| 2044 | Replicant                | New    | Normal   | Replicant 6.0                                 | Find offsets for other data (modem revision etc) and find where to get them from  |                        | 03/29/2021 03:40 PM | Telephony and mobile data | Unknown |                          |

| #    | Project                  | Status | Priority | Target version | Subject   | Assignee               | Updated             | Category    | Device   | Upstream patch status  |
|------|--------------------------|--------|----------|----------------|---|------------------------|---------------------|-------------|--|------------------------|
| 2043 | Replicant                | New    | Normal   | Replicant 6.0  | Investigate if it's possible to detect and recover EFS backups corrupted by 'adb shell "cat /dev/block/platform/*/by-name/efs" > /efs.img'                      |                        | 03/26/2021 05:10 PM |             | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250), Galaxy Note (GT-N7000), Galaxy Note (N7000), Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy Note 8.0 (N51xx), Galaxy S (I9000), Galaxy S 2 (I9100), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx), Nexus One, Nexus S (I902x) |                        |
| 2040 | Replicant                | New    | Normal   | Any version    | compare graphics performance between replicant-9 (no 3D acceleration) and replicant >= 10 (3D acceleration)   | Denis 'GNUtoo' Carikli | 03/27/2021 03:46 PM |             | Galaxy S 3 (I9300), Galaxy S 3 4G (I9305)  |                        |
| 2039 | Upstreaming patches      | New    | Normal   | Replicant 11.0 | Upstream the "Input: mms114: don't report 0 pressure while sliding" patch   | Denis 'GNUtoo' Carikli | 04/29/2024 09:58 PM | Linux       |  | Patches review started |
| 2038 | Replicant infrastructure | New    | Normal   |                | Add support for more distributions in the FSF vm creation script  |                        | 03/26/2021 05:07 PM |             |  |                        |
| 2036 | Replicant infrastructure | New    | Normal   |                | Enable to use other distributions than Trisquel on the FSF infrastructure   |                        | 04/29/2024 09:43 PM |             |  |                        |
| 2035 | Replicant infrastructure | New    | Normal   |                | Document the xml config file that is at <a href="https://autoconfig.replicant.us/mail/config-v1.1.xml">https://autoconfig.replicant.us/mail/config-v1.1.xml</a> | Denis 'GNUtoo' Carikli | 08/08/2021 11:23 PM |             |  |                        |
| 2032 | Upstreaming patches      | New    | Low      | Infrastructure | Make thunderbird work with our contact address  |                        | 04/29/2024 10:01 PM | Thunderbird |  | Work not started       |

| #    | Project   | Status | Priority | Target version     | Subject   | Assignee | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|--------|----------|--------------------|---|----------|---------------------|---------------------------|---|-----------------------|
| 2029 | Replicant | New    | Normal   | Replicant 6.0 0004 | Warn users that the modem_disable.sh disabling is lost after reflash                |          | 03/26/2021 04:58 PM | Website and wiki content  | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250), Galaxy Note (GT-N7000), Galaxy Note (N7000), Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy Note 8.0 (N51xx), Galaxy S (I9000), Galaxy S 2 (I9100), Galaxy S 3 (I9300), Nexus S (I902x)   |                       |
| 2028 | Replicant | New    | Normal   | Any version        | Make a script and/or a howto that explains how to rebuild an EFS.img from the files |          | 03/26/2021 04:56 PM | Telephony and mobile data | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250), Galaxy Note (GT-N7000), Galaxy Note (N7000), Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy Note 8.0 (N51xx), Galaxy S (I9000), Galaxy S 2 (I9100), Galaxy S 3 (I9300), Galaxy S 3 4G (I9305), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx), Nexus S (I902x) |                       |
| 2027 | Replicant | New    | Normal   | Replicant 6.0      | Investigate lthor / thor and samsung u-boot for Tizen                               |          | 05/05/2021 08:55 PM |                           | Unknown   |                       |
| 2026 | Replicant | New    | Normal   | Any version        | Review the Samsung Galaxy Xcover Pro  |          | 03/26/2021 04:52 PM | Devices                   | New device  |                       |

| #    | Project   | Status      | Priority | Target version     | Subject  | Assignee               | Updated             | Category                  | Device   | Upstream patch status |
|------|-----------|-------------|----------|--------------------|--|------------------------|---------------------|---------------------------|--|-----------------------|
| 2025 | Replicant | New         | Normal   | Any version        | Enable to recreate the EFS partition completely from scratch                               |                        | 04/20/2020 10:41 PM | Telephony and mobile data | Unknown  |                       |
| 2024 | Replicant | New         | Normal   | Any version        | Find offset and encoding of IMEI in the EFS for libsamsung-ipc                             |                        | 03/26/2021 04:48 PM | Telephony and mobile data | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250), Galaxy Note (GT-N7000), Galaxy Note (N7000), Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100), Galaxy Note 8.0 (N51xx), Galaxy S (I9000), Galaxy S 2 (I9100), Galaxy S 3 (I9300), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx), Nexus S (I902x) |                       |
| 2022 | Replicant | In Progress | Normal   | replicant 10.0     | Update our git to include forkbomb's u-boot midas updates.                                 | Denis 'GNUtoo' Carikli | 05/05/2021 07:56 PM | Bootloaders               | Unknown  |                       |
| 2016 | Replicant | New         | Normal   |                    | Document how to extract MLO  |                        | 03/26/2021 04:42 PM | Website and wiki content  |  |                       |
| 2015 | Replicant | New         | Normal   |                    | Document how to check MLO for signatures   |                        | 03/26/2021 04:40 PM | Website and wiki content  |  |                       |
| 2012 | Replicant | New         | Normal   | Replicant 6.0 0005 | Don't mount the HIDDEN partition   |                        | 03/27/2021 02:15 PM |                           |  |                       |
| 2011 | Replicant | New         | Normal   |                    | Find a public version of the MAX77693 datasheet / reference manual                         |                        | 06/02/2021 07:17 PM |                           |  |                       |
| 2010 | Replicant | New         | Normal   |                    | Find a public version of the DM3730 technical reference manual                             |                        | 03/26/2021 04:33 PM |                           |  |                       |
| 2007 | Replicant | New         | Normal   | Replicant 6.0      | sign-build: issue when building multiple times   |                        | 03/26/2021 04:26 PM |                           |  |                       |
| 2006 | Replicant | New         | Normal   | Replicant 6.0      | add drm_info to Replicant 6 and 9  |                        | 03/26/2021 04:26 PM |                           |  |                       |
| 2005 | Replicant | New         | Normal   | Replicant 6.0      | repos: check if there are still some default refs on replicant 4.x for replicant 6.0 repos |                        | 03/26/2021 04:24 PM | Infrastructure (web, git) |  |                       |

| #    | Project   | Status | Priority | Target version     | Subject   | Assignee    | Updated             | Category                                 | Device  | Upstream patch status |
|------|-----------|--------|----------|--------------------|---|-------------|---------------------|--|---|-----------------------|
| 2004 | Replicant | New    | Normal   | Replicant 6.0      | Investigate and document if it's possible to open encrypted USERDATA with luks on a desktop computer          |             | 03/13/2021 08:56 PM | Website and wiki content                 |   |                       |
| 2002 | Replicant | New    | Normal   | Replicant 6.0 0004 | Installation instructions: Handle different signing keys and make sure that the recovery match the zip        |             | 03/26/2021 04:21 PM | Installation instructions                |   |                       |
| 2000 | Replicant | New    | Normal   | replicant 10.0     | Make a debug recovery for Replicant 10  |             | 03/24/2021 01:41 AM |  |   |                       |
| 1999 | Replicant | New    | Normal   | Replicant 6.0      | Make a debug recovery for Replicant 6   |             | 03/24/2021 01:40 AM |  |   |                       |
| 1998 | Replicant | New    | High     | Any version        | Document "device encryption" Was: Replicant exposing parts of the system on boot even with encryption         |             | 03/24/2021 01:39 AM | Security                                 |   |                       |
| 1997 | Replicant | New    | Normal   | Replicant 6.0 0004 | Replicant 6.0 0004 RC1: Verify if usb tethering works   |             | 03/24/2021 01:38 AM |  |   |                       |
| 1995 | Replicant | New    | Normal   | Replicant 6.0      | Boot in loop during encryption  |             | 03/24/2021 01:49 PM |  | Galaxy S 3 (I9300)                              |                       |
| 1993 | Replicant | New    | Normal   | Replicant 6.0 0004 | Add generic instructions to find the gpg key associated with the release.                                     |             | 03/24/2021 01:36 AM | Installation instructions                |   |                       |
| 1992 | Replicant | New    | Normal   | Replicant 6.0      | Add note about optionally checking gpg signatures for the zip as well   |             | 03/24/2021 01:34 AM | Installation instructions                |   |                       |
| 1991 | Replicant | New    | Normal   | Replicant 6.0 0005 | Location on by default on first boot  |             | 03/24/2021 01:33 AM |  |   |                       |
| 1988 | Replicant | New    | Normal   | Replicant 6.0      | Safe mode is accidentally triggered too easily (Was "Safer" 'Safe Mode')                                      |             | 03/24/2021 02:01 PM |  | Galaxy S 3 (I9300)                              |                       |
| 1986 | Replicant | New    | Normal   | Replicant 6.0      | Safe mode can loose/erase data ('Safe Mode' purges accounts, and can also loose/erase application data)       |             | 03/24/2021 01:59 PM | Base applications                        | Galaxy S 3 (I9300)                              |                       |
| 1985 | Replicant | New    | Normal   |                    | Make documentation (text, video, presentation, etc) on how to get a Replicant compatible device in a DIY way. |             | 03/24/2021 01:29 AM | Website and wiki content                 |   |                       |
| 1984 | Replicant | New    | Normal   | Replicant 6.0 0004 | Add the 0004 release in the wiki  |             | 03/07/2021 11:45 AM | Website and wiki content                 |   |                       |
| 1983 | Replicant | New    | Normal   | Replicant 9.0      | Investigate LineageOS bug #1270 to see if there some upstream anti-features                                   |             | 03/24/2021 01:28 AM | Upstream antifeatures and privacy issues |   |                       |
| 1982 | Replicant | New    | Normal   | Replicant 6.0      | RepWifi not detecting wifi adapter  | Fil Bergamo | 03/24/2021 01:27 AM | RepWifi                                  | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100) |                       |
| 1981 | Replicant | New    | Normal   | Replicant 6.0 0005 | Investigate WiFi power consumption without RepWiFi  |             | 03/24/2021 01:26 AM | Wi-Fi                                    |   |                       |
| 1980 | Replicant | New    | Urgent   | Replicant 6.0 0005 | Meta bug for the SIM cards not being recognized   |             | 03/24/2021 03:04 PM |  |   |                       |

| #    | Project   | Status      | Priority | Target version      | Subject  | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|-------------|----------|---------------------|--|------------------------|---------------------|---------------------------|---|-----------------------|
| 1979 | Replicant | New         | Normal   | Replicant 6.0       | Make F-Droid Privileged Extention F-Droid signature match.   |                        | 03/24/2021 01:23 AM |                           |   |                       |
| 1978 | Replicant | In Progress | Normal   | Replicant 6.0 0005  | Backport Replicant 11 integration of F-Droid APK (Was "Find a good way to integrate APK from F-Droid") |                        | 03/24/2021 01:46 PM |                           |   |                       |
| 1975 | Replicant | New         | Normal   | Replicant 6.0       | Build Replicant 6.0 on PureOS amber  |                        | 03/24/2021 01:21 AM | Freedom                   |   |                       |
| 1973 | Replicant | New         | Normal   | Replicant 6.0 0005  | List the licenses of the various repositories in Replicant 6.0   | Denis 'GNUtoo' Carikli | 03/24/2021 01:21 AM | Freedom                   |   |                       |
| 1972 | Replicant | New         | Normal   | Replicant 6.0       | Camera error: Can't connect to the camera.   |                        | 03/24/2021 01:20 AM | Camera                    | Galaxy S 3 (I9300)                            |                       |
| 1971 | Replicant | New         | Normal   | Replicant 6.0       | SIM card not detected in i9300, but it works in dummy phone  |                        | 03/24/2021 01:37 PM | SIM card not recognized   | Galaxy S 3 (I9300)                            |                       |
| 1970 | Replicant | New         | Normal   | Replicant 6.0       | Error updating F-Droid and RepWifi   |                        | 03/24/2021 01:18 AM | Base applications         |   |                       |
| 1967 | Replicant | New         | Normal   | Replicant 6.0 0004  | recovery installation instructions: Add note about using sudo heimdall instead in some distributions   |                        | 03/07/2021 11:45 AM | Installation instructions |   |                       |
| 1966 | Replicant | New         | Normal   | Replicant 6.0 0004  | Wipe system partition after getting the files on the Replicant device                                  |                        | 03/07/2021 11:45 AM | Installation instructions |   |                       |
| 1965 | Replicant | New         | Normal   |                     | custom issue_statuses don't appear in the "Status" field when opening a new issue.                     |                        | 03/24/2021 01:15 AM | Infrastructure (web, git) |   |                       |
| 1964 | Replicant | New         | Normal   | Replicant 6.0       | Nothing happens when authorizing Mastodon account in Fedilab built-in browser                          |                        | 03/24/2021 01:14 AM |                           | Galaxy S 2 (I9100)                            |                       |
| 1958 | Replicant | In Progress | Normal   | Replicant 6.0       | Note II LTE modem (ofono Java RIL)   | Joey Hewitt            | 03/24/2021 01:08 AM | Telephony and mobile data |   |                       |
| 1957 | Replicant | New         | Normal   | Replicant 6.0 0005  | Add MHL support  |                        | 03/24/2021 01:06 AM |                           |   |                       |
| 1956 | Replicant | New         | Normal   | replicant 10.0      | move system.img and other images in out/target/product/<device>  |                        | 03/24/2021 01:04 AM |                           |   |                       |
| 1955 | Replicant | New         | Normal   | replicant 10.0      | Use one kernel image accross all midas boards  | Denis 'GNUtoo' Carikli | 03/24/2021 01:04 AM |                           |   |                       |
| 1954 | Replicant | In Progress | Normal   | Replicant 11.0 0001 | Add support for the I9300 modem  | Denis 'GNUtoo' Carikli | 02/03/2022 01:13 PM | Telephony and mobile data | Galaxy S 3 (I9300)                            |                       |
| 1953 | Replicant | New         | High     | Replicant 6.0       | Replicant 6.0 0003 Does Not Boot on I9250  |                        | 03/24/2021 01:01 AM | Website and wiki content  | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250) |                       |

| #    | Project   | Status      | Priority | Target version                                | Subject   | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|-------------|----------|---|---|------------------------|---------------------|---------------------------|---|-----------------------|
| 1951 | Replicant | New         | Normal   |   | Document more precisely GDPR compliance   |                        | 03/24/2021 01:00 AM | Infrastructure (web, git) |   |                       |
| 1950 | Replicant | New         | Normal   | Replicant 6.0 0005                            | Add Infrared (IR Blaster) support   |                        | 03/24/2021 12:59 AM |                           |   |                       |
| 1949 | Replicant | In Progress | Normal   | Replicant 6.0 0005                            | Make web browser and email client support TLS 1.2   |                        | 03/24/2021 12:58 AM | Base applications         | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100) |                       |
| 1948 | Replicant | New         | Normal   |   | Document how to install and run Replicant in a virtual machine  |                        | 03/24/2021 12:56 AM | Installation instructions |   |                       |
| 1947 | Replicant | New         | Normal   | Replicant 6.0 0005                            | Ask upstream F-Droid to build up to date WebView  |                        | 03/07/2021 11:50 AM | Graphics                  |   |                       |
| 1946 | Replicant | New         | Normal   | Any Replicant version with an upstream kernel | Add support for the Note 10.1 (2012 edition)  |                        | 04/01/2021 05:30 PM | Devices                   |   |                       |
| 1945 | Replicant | New         | Normal   | Any version                                   | Evaluate more in depth the android_frameworks_opt_telephony_ril_ofono RIL                                     | Fil Bergamo            | 03/24/2021 12:53 AM | Telephony and mobile data |   |                       |
| 1943 | Replicant | New         | Normal   | replicant 10.0                                | Tune media player for software rendering  | dl lud                 | 03/24/2021 01:36 PM | Graphics                  |   |                       |
| 1938 | Replicant | New         | Normal   | Replicant 6.0 0005                            | Add the Offline Calendar app by default   | Andrés D               | 03/24/2021 12:50 AM | Base applications         |   |                       |
| 1937 | Replicant | New         | Normal   | Replicant 6.0                                 | Liberate the bcm4334 wifi/bluetooth firmware  |                        | 03/26/2021 11:10 PM | Wi-Fi                     |   |                       |
| 1936 | Replicant | New         | Normal   |   | Make branch and manifest with changes being reviewed on the mailing list                                      | Denis 'GNUtoo' Carikli | 03/24/2021 12:44 AM |                           |   |                       |
| 1934 | Replicant | New         | Normal   | Replicant 6.0 0005                            | recovery: harmonize fstab   |                        | 03/24/2021 12:41 AM | Installation instructions |   |                       |
| 1933 | Replicant | New         | Normal   |   | Make the EFS mount point the same accross all devices   |                        | 03/24/2021 12:40 AM | Installation instructions |   |                       |
| 1928 | Replicant | New         | Normal   | Replicant 6.0                                 | Bluetooth is working on several devices when it shouldn't   |                        | 10/09/2021 10:51 PM | Freedom                   |   |                       |
| 1926 | Replicant | New         | Normal   | Any version                                   | Maxim Power Management ICs: find how much mA it can provide, and check if it's configurable                   | Denis 'GNUtoo' Carikli | 10/24/2021 11:44 AM | Wi-Fi                     |   |                       |
| 1925 | Replicant | Feedback    | Normal   | Replicant 6.0                                 | On the Galaxy SII, the GPS isn't supposed to work, but OSMAnd is able to get a position in "device only" mode |                        | 03/24/2021 12:48 AM | Freedom                   |   |                       |
| 1924 | Replicant | New         | Normal   |   | libsamsung-ipc: flight mode: don't enable the modem when in flight mode at boot                               |                        | 03/24/2021 12:34 AM | Telephony and mobile data |   |                       |

| #    | Project   | Status | Priority  | Target version                                | Subject   | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|--------|-----------|---|---|------------------------|---------------------|---------------------------|---|-----------------------|
| 1920 | Replicant | New    | Normal    | Replicant 6.0                                 | RuntimeException: Camera is being used after Camera.release() was called  |                        | 03/24/2021 12:34 AM | Camera                    |   |                       |
| 1919 | Replicant | New    | Normal    | Replicant 6.0                                 | Unable to install the recovery image to the device.   |                        | 03/24/2021 12:32 AM |                           | Galaxy S 3 (I9300)                              |                       |
| 1917 | Replicant | New    | Normal    | Replicant 6.0 0005                            | Add more robust fstab handling  |                        | 03/24/2021 12:31 AM |                           |   |                       |
| 1916 | Replicant | New    | Normal    |   | Write instructions to migrate from self-build images to releases (Was: Write upgrade instructions from Replicant 6.0 0003 to Replicant 6.0 0004 (incompatible /data partition)) | Fil Bergamo            | 03/24/2021 12:27 AM | Website and wiki content  |   |                       |
| 1915 | Replicant | New    | Normal    | Replicant 6.0 0004                            | publish the Replicant 6.0 0004 release blog post  |                        | 03/07/2021 11:44 AM | Website and wiki content  |   |                       |
| 1913 | Replicant | New    | Normal    | Replicant 6.0 0005                            | f-droid: create an interim solution   | Denis 'GNUtoo' Carikli | 03/24/2021 12:26 AM | Freedom                   |   |                       |
| 1911 | Replicant | New    | Normal    | Replicant 6.0                                 | Samsung Keyboard Dock works for encryption password entry, stops working once Replicant is loaded   |                        | 03/24/2021 12:25 AM |                           |   |                       |
| 1910 | Replicant | New    | Normal    | Replicant 6.0 0005                            | Unfortunately, Shattered Pixel Dungeon has stopped.   |                        | 03/24/2021 12:23 AM | Graphics                  |   |                       |
| 1906 | Replicant | New    | Normal    | Any Replicant version with an upstream kernel | Replace S-Boot with U-Boot on exynos4412 (midas) devices  |                        | 05/05/2021 08:27 PM |                           |   |                       |
| 1905 | Replicant | New    | Normal    | Replicant 6.0                                 | Camera error: Can't connect to the camera [erase app data fail]   |                        | 03/24/2021 12:21 AM | Camera                    | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100) |                       |
| 1901 | Replicant | New    | Low       | Any version                                   | Add/Fork Prism Break to the replicant wiki  |                        | 03/24/2021 12:18 AM |                           |   |                       |
| 1900 | Replicant | New    | Normal    | Any version                                   | supported-devices.php: outdated pictures  | Fil Bergamo            | 03/24/2021 12:15 AM | Website and wiki content  |   |                       |
| 1899 | Replicant | New    | Low       | Replicant 6.0                                 | complete website information about supported device   |                        | 03/24/2021 12:13 AM | Website and wiki content  |   |                       |
| 1894 | Replicant | New    | Normal    | Replicant 6.0                                 | Settings app broken   |                        | 03/24/2021 12:12 AM |                           |   |                       |
| 1888 | Replicant | New    | Low       | Replicant 6.0                                 | Add a bot to our IRC  |                        | 03/24/2021 12:11 AM | Infrastructure (web, git) |   |                       |
| 1881 | Replicant | New    | Normal    |   | Install a patchwork instance somewhere to track patches   |                        | 03/24/2021 12:10 AM | Infrastructure (web, git) |   |                       |
| 1878 | Replicant | New    | Immediate | Any version                                   | Make f-droid be FSDG compliant again to be able to include it again in Replicant  |                        | 03/24/2021 12:09 AM | Freedom                   |   |                       |



| #    | Project   | Status      | Priority | Target version     | Subject  | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|-------------|----------|--------------------|--|------------------------|---------------------|---------------------------|---|-----------------------|
| 1877 | Replicant | New         | Normal   |                    | redmine: don't require user first and last names   |                        | 03/24/2021 12:09 AM | Infrastructure (web, git) |   |                       |
| 1875 | Replicant | New         | Normal   | Replicant 6.0      | No service after entering flight mode  |                        | 03/24/2021 12:06 AM | Telephony and mobile data | Galaxy S 2 (I9100)                              |                       |
| 1874 | Replicant | New         | Normal   | Replicant 6.0      | Samsung Galaxy Note II SIM Vodafone Spain, not detected  | Paul Kocalkowski       | 03/24/2021 12:05 AM | SIM card not recognized   |   |                       |
| 1873 | Replicant | New         | Normal   | replicant 10.0     | Remove UMS partition   |                        | 03/24/2021 12:01 AM |                           | Galaxy S 2 (I9100)                              |                       |
| 1871 | Replicant | New         | Normal   | Replicant 6.0      | Italian SIM Wind not recognised  |                        | 03/23/2021 11:59 PM | SIM card not recognized   | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100) |                       |
| 1869 | Replicant | New         | Normal   | Replicant 6.0      | Investigate the creation of nv_data.bin by the nonfree RIL   |                        | 03/23/2021 11:55 PM | Telephony and mobile data |   |                       |
| 1868 | Replicant | New         | Normal   | Replicant 6.0      | SIM not detected   |                        | 03/23/2021 11:53 PM | SIM card not recognized   | Galaxy S 2 (I9100)                              |                       |
| 1866 | Replicant | New         | Normal   | Replicant 6.0      | Support devices with upstream GNU/Linux support  |                        | 03/23/2021 11:50 PM |                           |   |                       |
| 1863 | Replicant | New         | Normal   | Replicant 6.0      | maven-debian-helper dropped mvn-debian, so did debian sid and PureOS   |                        | 03/23/2021 11:48 PM | Build system              |   |                       |
| 1861 | Replicant | In Progress | Normal   | Replicant 6.0 0005 | Recommend to use an FSDG compliant distribution to build Replicant   |                        | 09/23/2022 09:29 PM | Freedom                   |   |                       |
| 1858 | Replicant | New         | Normal   | Replicant 6.0      | Camera functionality doesn't work in a lot of apps   |                        | 03/24/2021 12:03 AM | Camera                    |   |                       |
| 1854 | Replicant | New         | Normal   | Replicant 6.0      | Device not rebooting after 5 unsuccessful unlock attempts  |                        | 03/23/2021 11:45 PM | Security                  | Galaxy S 3 (I9300)                              |                       |
| 1852 | Replicant | New         | Normal   | Replicant 6.0      | No SIM - SIM unknown for Replicant 6.0 - Works for Replicant 4.2 0004 without an issue - SIM not recognized / unrecognized - PHONE i9300 |                        | 03/23/2021 11:43 PM | SIM card not recognized   | Galaxy S 3 (I9300)                              |                       |
| 1851 | Replicant | New         | Normal   | Replicant 6.0      | heimdall 1.4.1 fails to upload a new kernel on SGS2 (i9100)  |                        | 03/23/2021 11:42 PM |                           | Galaxy S 2 (I9100)                              |                       |
| 1849 | Replicant | New         | Normal   | Replicant 6.0      | SIM card does not work after device encryption   |                        | 03/23/2021 11:41 PM | SIM card not recognized   | Galaxy Tab 2 7.0 (P31xx)                        |                       |
| 1847 | Replicant | New         | Normal   | Replicant 6.0 0005 | Toolchain build failure as it expect certain tools in /usr/bin instead of /bin   | Denis 'GNUtoo' Carikli | 03/23/2021 11:40 PM | Build system              |   |                       |
| 1846 | Replicant | New         | Normal   | Replicant 6.0 0005 | Toolchain build failure when /usr/lib64/libxml2.so is not present  | Denis 'GNUtoo' Carikli | 03/23/2021 11:39 PM | Build system              |   |                       |

| #    | Project   | Status   | Priority | Target version     | Subject  | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|----------|----------|--------------------|--|------------------------|---------------------|---------------------------|---|-----------------------|
| 1845 | Replicant | New      | Urgent   | Replicant 6.0      | Matching nv_data md5 failed after I got my cellphone unlocked (I have a efs backup)                  |                        | 03/23/2021 11:38 PM |                           | Galaxy S 2 (I9100)                              |                       |
| 1843 | Replicant | New      | Normal   | Replicant 6.0      | setprop wrap causes Replicant to reboot when wrapped app is launched                                 |                        | 03/23/2021 11:35 PM |                           | Galaxy S 3 (I9300)                              |                       |
| 1842 | Replicant | New      | Normal   | Replicant 6.0      | SIM Card Not Recognised (GT-N7100)   |                        | 03/23/2021 11:33 PM | SIM card not recognized   | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100) |                       |
| 1838 | Replicant | New      | Normal   | Replicant 6.0      | Replicant 6 not responsive   |                        | 03/23/2021 11:32 PM | Graphics                  | Galaxy S 3 (I9300)                              |                       |
| 1834 | Replicant | New      | Normal   | Replicant 6.0 0005 | I9305 suddenly reboots (modem related)   |                        | 03/23/2021 11:28 PM | Telephony and mobile data | Galaxy S 3 4G (I9305)                           |                       |
| 1833 | Replicant | New      | Normal   | replicant 10.0     | Add possibility to update Replicant from within Replicant / OTA / Over The Air                       |                        | 03/23/2021 11:27 PM | Base applications         |   |                       |
| 1831 | Replicant | New      | Normal   |                    | Fix non-idempotent setup.sh  | Wolfgang Wiedmeyer     | 03/23/2021 05:53 PM | Wi-Fi                     |   |                       |
| 1828 | Replicant | New      | Normal   | Replicant 6.0      | Document upstream antifeatures   |                        | 03/23/2021 05:51 PM | Website and wiki content  |   |                       |
| 1824 | Replicant | New      | Normal   | Replicant 6.0      | italian fastweb SIM card not recognized  |                        | 03/23/2021 05:51 PM | SIM card not recognized   |   |                       |
| 1822 | Replicant | New      | Normal   | Any version        | Formalize bounty system  |                        | 03/23/2021 05:50 PM |                           |   |                       |
| 1820 | Replicant | New      | Normal   | Any version        | Do some testing on femtocells  | Denis 'GNUtoo' Carikli | 03/23/2021 05:46 PM | Website and wiki content  |   |                       |
| 1819 | Replicant | New      | Normal   | Replicant 6.0      | radiooptions command is returning an error   | Wolfgang Wiedmeyer     | 07/18/2017 07:05 PM | Telephony and mobile data | Galaxy S 2 (I9100)                              |                       |
| 1817 | Replicant | Feedback | Normal   | Replicant 6.0      | loose root access and developer options  | Fil Lupin              | 03/23/2021 05:41 PM | Framework                 | Galaxy S 3 (I9300)                              |                       |
| 1816 | Replicant | Feedback | High     | Replicant 6.0      | "Encrypt Phone" crashes and sometimes sends the phone into a boot loop                               | Harry Prevor           | 03/27/2021 11:13 AM | Security                  | Galaxy S 3 (I9300)                              |                       |
| 1813 | Replicant | New      | Normal   | Replicant 6.0      | Modem support for i9305  | Wolfgang Wiedmeyer     | 03/23/2021 05:32 PM | Telephony and mobile data | Galaxy S 3 4G (I9305)                           |                       |
| 1809 | Replicant | New      | High     | Replicant 6.0      | No SIM card No service reported but sim present  |                        | 12/12/2019 05:47 PM | SIM card not recognized   | Galaxy S 3 (I9300)                              |                       |
| 1806 | Replicant | New      | Normal   | Any version        | modem shell enable/disable script: verify with measurements through a BTS that the modem is disabled |                        | 03/23/2021 05:30 PM | Telephony and mobile data |   |                       |
| 1804 | Replicant | New      | Normal   | Replicant 6.0      | Add back menu entries and disable back button  | Wolfgang Wiedmeyer     | 03/23/2021 05:29 PM | Recovery                  |   |                       |

| #    | Project   | Status   | Priority | Target version      | Subject   | Assignee               | Updated             | Category                  | Device  | Upstream patch status |
|------|-----------|----------|----------|---------------------|---|------------------------|---------------------|---------------------------|---|-----------------------|
| 1803 | Replicant | Feedback | Normal   | Replicant 6.0       | Error-prone and confusing touchscreen interface in recovery   | Wolfgang Wiedmeyer     | 03/23/2021 05:28 PM | Recovery                  |   |                       |
| 1802 | Replicant | New      | Normal   | Replicant 6.0       | Replicant 6.0 recovery lacks backup features  |                        | 03/23/2021 05:27 PM | Recovery                  |   |                       |
| 1798 | Replicant | New      | Normal   | Replicant 6.0       | After Factory Reset, I only Have 1.96GB   | Wolfgang Wiedmeyer     | 03/23/2021 05:24 PM | Website and wiki content  | Galaxy S 2 (I9100)                              |                       |
| 1797 | Replicant | New      | Low      | Replicant 6.0 0005  | Create a boot animation   |                        | 01/24/2022 12:27 PM | Framework                 |   |                       |
| 1793 | Replicant | New      | Normal   |                     | Consider locking critical wiki pages  | Wolfgang Wiedmeyer     | 03/23/2021 05:18 PM | Website and wiki content  |   |                       |
| 1791 | Replicant | New      | Normal   | Replicant 6.0       | [RepWifiApp] Instable interface wlan0 on i9100  |                        | 03/23/2021 05:13 PM | Wi-Fi                     | Galaxy S 2 (I9100)                              |                       |
| 1790 | Replicant | New      | Normal   | Replicant 6.0       | Trebuchet crash when using 'folders'  |                        | 03/23/2021 05:10 PM | Base applications         |   |                       |
| 1788 | Replicant | New      | High     | Any version         | Ensure that emergency calls work properly   |                        | 03/23/2021 11:52 AM | Telephony and mobile data |   |                       |
| 1786 | Replicant | Feedback | Normal   | Replicant 6.0 0005  | Review the Chromium Webview build environment   | Andrés D               | 03/23/2021 03:05 PM | Freedom                   |   |                       |
| 1785 | Replicant | New      | Low      | Replicant 6.0 0005  | Change the app label of the old Gallery app   |                        | 03/23/2021 11:49 AM | Base applications         |   |                       |
| 1784 | Replicant | New      | Normal   | Replicant 6.0 0005  | Integrate toolchain build in Android build system   |                        | 03/23/2021 11:47 AM | Build system              |   |                       |
| 1783 | Replicant | Feedback | Urgent   | Replicant 6.0       | SIM card not recognized (regression, was working with Replicant 4.2)  | Wolfgang Wiedmeyer     | 03/23/2021 03:09 PM | SIM card not recognized   | Galaxy S 3 (I9300)                              |                       |
| 1780 | Replicant | New      | Urgent   | Replicant 6.0 0005  | Update the webview apk  | Andrés D               | 05/29/2021 02:28 AM | Security                  |   |                       |
| 1779 | Replicant | New      | Normal   | Replicant 6.0 0005  | Implement setting that allows to permanently disable the modem  | Fil Bergamo            | 03/23/2021 11:28 AM | Telephony and mobile data |   |                       |
| 1777 | Replicant | New      | High     | Replicant 6.0 0005  | Connecting headset to i9300 is saturated the person your are calling speaker                                      |                        | 03/23/2021 03:05 PM | Telephony and mobile data | Galaxy S 3 (I9300)                              |                       |
| 1776 | Replicant | New      | Normal   | libsamsung-ip c 1.0 | Write tool to strip off privacy sensitive information from "logcat -b radio"                                      | Denis 'GNUtoo' Carikli | 04/04/2022 12:54 PM | Telephony and mobile data |   |                       |
| 1773 | Replicant | New      | Urgent   | Replicant 6.0 0005  | Metalic and horrible sound quality when call are made through 3G network / Replicant 4.2 & 6.0 on I9300 and N7100 |                        | 07/03/2021 04:57 PM | Telephony and mobile data |   |                       |
| 1755 | Replicant | Feedback | Normal   | Replicant 6.0       | GT-N7100 sensors don't work   | CyberLeo Kitsana       | 03/23/2021 03:00 PM | Sensors                   | Galaxy Note 2 (GT-N7100), Galaxy Note 2 (N7100) |                       |

| #    | Project   | Status      | Priority  | Target version      | Subject   | Assignee           | Updated             | Category                                 | Device             | Upstream patch status |
|------|-----------|-------------|-----------|---------------------|---|--------------------|---------------------|--|--------------------|-----------------------|
| 1659 | Replicant | In Progress | High      |                     | The device pages don't warn about proprietary (and likely signed) TrustZone TEE | Paul Kocialkowski  | 03/23/2021 11:15 AM | Website and wiki content                 |                    |                       |
| 1653 | Replicant | Feedback    | Low       | Any version         | Noise Based Auto Profile Switcher   | Akshit Mahajan     | 03/23/2021 02:59 PM | Audio                                    |                    |                       |
| 1635 | Replicant | In Progress | Immediate | Any version         | F-droid Antifeature:NonFreeAssets wiki page is unclear                          | Wolfgang Wiedmeyer | 03/23/2021 11:09 AM | Upstream antifeatures and privacy issues |                    |                       |
| 1629 | Replicant | In Progress | Immediate | Any version         | F-Droid does not respect the GNU free system distributions guidelines           |                    | 03/23/2021 11:09 AM | Freedom                                  |                    |                       |
| 1605 | Replicant | New         | High      | Replicant 6.0       | SIM card not recognized GT-i9300 (modem crash)                                  | Paul Kocialkowski  | 03/23/2021 03:04 PM | Telephony and mobile data                | Galaxy S 3 (I9300) |                       |
| 1539 | Replicant | New         | Normal    | Replicant 6.0       | Graphics acceleration   |                    | 03/23/2021 11:03 AM | Graphics                                 |                    |                       |
| 1533 | Replicant | New         | Normal    | Replicant 6.0       | Broken video playback in the browser  |                    | 03/23/2021 02:56 PM | Graphics                                 |                    |                       |
| 1521 | Replicant | New         | Normal    | Replicant 6.0       | Video decoding support  |                    | 03/23/2021 03:24 PM | Media encoding/decoding                  |                    |                       |
| 1515 | Replicant | New         | Normal    | Any version         | Support for more video software-decoding codecs                                 | Paul Kocialkowski  | 03/23/2021 10:52 AM | Media encoding/decoding                  |                    |                       |
| 1509 | Replicant | New         | Normal    | Replicant 6.0       | Software video decoding support   |                    | 03/23/2021 03:02 PM | Media encoding/decoding                  |                    |                       |
| 1497 | Replicant | New         | Normal    | Any version         | Missing audio scenarios for bluetooth   | Paul Kocialkowski  | 03/23/2021 10:50 AM | Audio                                    | Galaxy S 2 (I9100) |                       |
| 1491 | Replicant | New         | Normal    | Replicant 11.0 0001 | Hardware-specific graphics acceleration   |                    | 03/23/2021 02:55 PM | Graphics                                 |                    |                       |
| 1485 | Replicant | New         | High      | Any version         | Samsung-RIL missing features  | Paul Kocialkowski  | 03/23/2021 10:47 AM | Telephony and mobile data                |                    |                       |
| 1479 | Replicant | New         | Normal    | Any version         | GSD4t GPS support   |                    | 03/23/2021 10:46 AM | GPS                                      |                    |                       |
| 1473 | Replicant | New         | Normal    | Any version         | BCM4751 GPS support   |                    | 03/25/2021 03:32 PM | GPS                                      |                    |                       |
| 1275 | Replicant | New         | Normal    | Replicant 6.0 0005  | Screen content (shortly) visible before unlocking                               |                    | 03/23/2021 03:00 PM | Security                                 |                    |                       |
| 1215 | Replicant | New         | Normal    | Any version         | REQUEST_GET_NEIGHBORING_CELL_IDS error: REQUEST_NOT_SUPPORTED                   | Paul Kocialkowski  | 03/23/2021 10:33 AM | Telephony and mobile data                |                    |                       |
| 1149 | Replicant | New         | Low       | Replicant 6.0       | Image gets "broken" when putting samsung galaxy s3 in landscape position        | Paul Kocialkowski  | 03/23/2021 03:00 PM | Framework                                | Galaxy S 3 (I9300) |                       |

| #    | Project   | Status      | Priority | Target version | Subject   | Assignee           | Updated             | Category                  | Device   | Upstream patch status |
|------|-----------|-------------|----------|----------------|---|--------------------|---------------------|---------------------------|--|-----------------------|
| 1125 | Replicant | New         | Normal   | Replicant 6.0  | The "additional settings" option in the "phone" application doesn't work. | Paul Kocialkowski  | 03/23/2021 02:58 PM | Framework                 | Not device specific  |                       |
| 1017 | Replicant | New         | Normal   | Any version    | Sim ToolKit (STK) support is missing                                      | Paul Kocialkowski  | 03/23/2021 03:19 PM | Telephony and mobile data |  |                       |
| 1011 | Replicant | In Progress | Normal   | Any version    | USSD codes don't work   | Wolfgang Wiedmeyer | 03/23/2021 10:29 AM | Telephony and mobile data |  |                       |
| 939  | Replicant | Feedback    | Normal   | Replicant 6.0  | Phonecall terminates without busy signal                                  |                    | 03/23/2021 02:55 PM | Telephony and mobile data |  |                       |
| 837  | Replicant | New         | Normal   | Any version    | Replicant Native Development Kit (NDK) build and release                  |                    | 03/23/2021 10:13 AM | Build system              |  |                       |
| 351  | Replicant | New         | Low      | Replicant 6.0  | Camera and video recording support  | Paul Kocialkowski  | 08/08/2021 11:30 PM | Camera                    | Galaxy Nexus (GT-I9250), Galaxy Nexus (I9250), Galaxy Tab 2 10.1 (P51xx), Galaxy Tab 2 7.0 (P31xx) |                       |