

Issues

#	Project	Status	Priority	Target version	Subject	Assignee	Updated	Category	Device	Upstream patch status
1854	Replicant	New	Normal	Replicant 6.0	Device not rebooting after 5 unsuccessful unlock attempts		03/23/2021 11:45 PM	Security	Galaxy S 3 (I9300)	
1843	Replicant	New	Normal	Replicant 6.0	setprop wrap causes Replicant to reboot when wrapped app is launched		03/23/2021 11:35 PM		Galaxy S 3 (I9300)	
1831	Replicant	New	Normal		Fix non-idempotent setup.sh	Wolfgang Wiedmeyer	03/23/2021 05:53 PM	Wi-Fi		
1813	Replicant	New	Normal	Replicant 6.0	Modem support for i9305	Wolfgang Wiedmeyer	03/23/2021 05:32 PM	Telephony and mobile data	Galaxy S 3 4G (I9305)	